

Simpson Road Bridge Update
January 23, 2017



View of Simpson Road bridge crossing over Stackpole Creek from Buxton side looking across bridge towards the Saco approach. Contractor is placing sub base gravel material within the roadway section. Remaining work prior to the end of the month will include installation of Jersey barriers along each side of the roadway to permit re-opening to emergency vehicles.

Photo taken on January 23, 2017.



View of upstream side of Simpson Road bridge crossing over Stackpole Creek. Cast-in-place and precast concrete retaining wall structure installation is complete. Remaining work includes installation of masonry veneer exterior surface to match the protruding stones of the key-way arch.

Photo taken on January 23, 2017.